




American Retail Supply Assembly Instructions

Paxar-Monarch Label Loading

1130 (81030), 1131 (81031), 1135 (82035), 1136 (82036, 82037),
1151 (86051), 1152 (86052), 1153 (81502)

Loading Labels



1) Pull the latches back and swing the cover open completely. You should hear a click. Don't force the cover past the click position.

2) For loading a new roll of supply, tear off and discard the first 10 inches of labels and liner.

3) Place the label roll between the holders.

4) Drape the supply across the labeler and center it over the peel bar.

Do not thread label strip through any rollers. The supply should hang out 5-6 inches past the peel bar.

5) Close the cover.

6) Hold the labeler upside down. Squeeze and hold the trigger. Feed the label strip over the roller and into the large slot under the arrows.

Hold the strip in place and squeeze the trigger eight times until the label strip feeds through the rear exit. Remove any loose labels.



(800) 426-5708 • www.MakeYouHappy.com

Packaging • Display • Price Marking
Inventory Control • Promotional Products